

STATINTL

RDP67B00511R000190004-7

DOC. NO.	535
TOTAL PAGES	5
COPY	5 OF 9

16 June 1964

OSA -2975-64

STATINTL

TO:

STATINTL

FROM:

REF: Area 6217 (10 Jun 64) Para. 7. Task 2030

Attachments #1 (one sheet), #2 (two sheets) and #3 (one sheet) contain our available file background on the Vac-Ion pump power being fed through Plug Q5.

The 13 Sep 63 phonecon (Att. 1) led to [REDACTED] 18 Sep 63 letter to me (Att. 2-A and 2-B). Since we have received no amendment to Don's letter, all our systems are wired to accommodate the schematic (Att. 2-B). Per my notes of 7 Oct 63 meeting with Don (Att. 3), only the fuse shown in the schematic was eliminated. STATINTL

Since frame rewiring is time consuming and expensive, we propose to (1) leave our system as it is now and (2) have [REDACTED] wire plug Q5 in accordance with the agreement. If this proposed course is impossible, we will investigate alternative courses, but any alternative will have to be new scope contractually. STATINTL

STATINTL

mb STATINTL

cc: